2020 FLASHLIGHT / 2680 HEADLAMP SUGGESTED REPLACEMENTS

TECH BULLETIN | 05/13/2019





In an effort to keep the Pelican™ lighting line fresh and innovative, we will be discontinuing a number of older products. The list below details two of those models and suggested replacements. We hope this advance notice will allow for any necessary adjustments in your marketing materials and order placements. We will attempt to support these items up to July 31, 2019, however, some models have limited quantities and will be treated as "while supplies last".

THE RESIDENCE TO SERVICE TO SERVI	The state of the s	C PELICAN 3345
Discontinued	Suggested Replacement	Suggested Replacement
2020 Flashlight	3315 Flashlight	3345 Flashlight
 C Batteries (Not Included): 3 Safety Certified: Class I Div. 1, Class I Div. 2 Lumens: 75 Run Time: 6 Hours, 30 Minutes 	 AA Batteries (Included): 3 Safety Certified: Class I, II, III, Div. 1 / IECEx ia Lumens: 160 Run Time: 19 Hours 	 AA Batteries (Not Included): 3 Safety Certified: Class I,II,III, Div. 1 / IECEx ia Lumens: 280 Run Time: 7 Hours
	PRICAN-	K K K K K K K K K K K K K K K K K K K
Discontinued	Suggested Replacement	Suggested Replacement
2680 Headlamp	2765 Headlamp	2785 Headlamp
 AA Batteries (Included): 4 Safety Certified: Class I,II,III, Div. 2 Lumens: 79 Run Time: 10 Hours 	 AAA Batteries (Included): 3 Safety Certified: Class I, Div. 1 / IECEx ia Lumens: 155 Run Time: 6 Hours, 15 Minutes 	 AA Batteries (Included): 4 Safety Certified: Class I, Div.1 / IECEx ia Lumens: 215 Run Time: 5 Hours

Pelican Products, Inc. 23215 Early Avenue, Torrance, CA 90505 Tel: (310) 326-4700 • Toll Free (800) 473-5422