ELECTRICAL SAFETY RECALL

Pelican NiMH Flashlights

Model Numbers 9410 and 9415



IDENTIFICATION:

Model number 9410 - available for sale from January 2010 to December 2013 Model number 9415 - available for sale from June 2013 to August 2019

Model numbers 9410L and 9415iY are not affected.

Consumers should check the decal on the handle area of the flashlight (shown above), which states the model or catalog number. The individual charger and products and their labels show the catalog or model number (shown above).

DEFECT: The Battery Pack for the Flashlight may become unstable, overheat and explode while charging.

HAZARD: If the Battery Pack explodes it may propel fragments outwards with significant force, potentially causing an injury.

WHAT TO DO: Consumers should stop charging and using the products and return them for a replacement Battery Pack or Flashlight.

For further information about the recall visit http://www.pelican.com/9410-9415-recall-au

CONTACT DETAILS: For further information, contact Pelican by phone on 02 4367 7022 (Monday to Friday 8.30AM to 5PM AEST) or email info.australia@pelican.com.

See www.productsafety.gov.au
for Australian product recall information

SAFETY RECALL

Pelican 9410 and 9415 NiMH Flashlights can Become Unstable and Explode while Charging, creating a Risk of Injury.

Stop Charging and Using the Flashlight Immediately





To identify recalled products without the original packaging, check the decal on the handle area that states the model or catalogue number.

For the individual charger and product, the labels show the catalogue or model number (see on left).

Contact Pelican, 8:30AM-5 PM, Monday through to Friday at 02 4367 7022, or info.australia@pelican.com for more information and instructions regarding this recall.

*Note: 9410L, 9415i & 9415 ZO are NOT included in this safety recall.